

Historic New Market, Maryland

1969 Survey

(This group of houses situated

(on NORTH SIDE OF MAIN STREET

and proceeding West from Federal

and Main to the Western Limit of
the Historic Area.

(

(

(




1.
Federal & Main St.
North Side


Owner -
Charles A. Jackson
One-family dwelling

Original owner - George Smith
House used as an early inn
Weatherboard
Circa 1800

Post-Colonial

Good style
No or little disecration
Good physical condition






Present Owner - Mrs. Catherine Miller
One Family

Federal - 1800-1830
Fair Style
Considerable Change
Good condition



Prospect Alley & Main
East Side



Owner - Jane Downey
 Original Use - Dwelling & Store
 Presently one family-dwelling

Federal - 1825


Good style

No or little change

Good condition

Jesse Wright built & operated the store fronting Main Street circa 1825. Back of building built much earlier.

Front of dwelling operated as a button factory before the store was built. Legend has it that the Angamone Mounted Rifles, disbanded at the start of the Civil War, cached their weapons in the outhouses on the property, where they were confiscated & discovered by the Union soldiers.



Dweller - Jane Douray
 Dwelling
 Revival - 1850

Good style
 No or little change
 Good condition



Renual


1. Front door is on one side -
Federal doors and earlier were
usually central feature.

2. Lines around door are "long and
nestical. Trimming is simple.

3. I didn't read this fact anywhere,
but this house is different in that
it has 2 chimneys on one side
of the house.



4



Owner - Franklin Rappold
Original Use - Dwelling &
Post Office in 1798.

Present Use - One family
Commercial

Federal 1800 - 1830

Good style

Moderate amt. of change

Good condition

This property had many
uses, among them, as
a tavern and as
early as 1840 a
full blown Hotel,
the National Hotel.

Description

1. Elliptical fan door with side windows also

2. Wrought iron railings.

3. Two interior end chimneys

4. Over windows - end blocks with center block -
triangular section over windows on lower floor



7.

Owner -

W. Franklin Smith

One family


Weatherboard

Victorian 1835-190


Good style

NB or little change

Good condition



Masonic Lodge - Strawberry Alley & Main St.



8.

Owner - Ray Massanelle
Original Use - Dwelling
Present Use - Dwelling -
One family & Commercial



Weatherboard

Federal 1800-1830

Good style

Considerable change

Excellent condition



Owner - Mr. & Mrs. Morse Prosser

Original Owner - Anthony Poulter

Owned by Jesse Wright in 1836

Present Use - One family

Stone, brick & weatherboard


Year Built - 1803

Federal 1800-1830

Excellent style

Moderate amt of change


Good condition



Owner - Mr. & Mrs. Arthur Esworthy
 Brick and Weatherboard
 Two Family - Present

Brick 1798 -
 Weatherboard - 1890

Post-Colonial - Victorian
 Good Style
 Moderate Amt. of Change
 Excellent Condition



Owner - Mr. Jesse Burrall

Owner family

Architect or Builder - Mrs. Mary Burrall

Brick - 1880

Victorian

Exceptional style

No or little change

Good condition






15

Owner - Mr. & Mrs. Paul C. Wolff
One family - Commercial

Weatherboard circa 1820

Federal
Fair Style
Considerable Change
Needs Repairs





Present Owner - Mr. & Mrs. Vankub Fehr

One family dwelling - Commercial

Original Owner - Plummer

Architect or builder - Plummer

Log & Weatherboard

circa 1770

Colonial

Excellent style

Moderate amt. of change

Good condition



This house was the farm house
on the Plummer tract before
New Market was laid out.

Built by Plummer for his
bride.

✓

Description

1. End chimney plan used (Great improvement to houses in early times)
2. Wood house, (2nd in use was brick) (Wood popular in New England wood usually allowed to weather, sometimes dark green was used - this building is a dull green. Wooden houses had overlapping or dropped siding)
3. Doorway is central and featured.
Pilasters aren't large, but are used just the same.
4. Pediment over door (broken pediment used in that time).
5. Window type is example of early nineteenth century window in Providence, R.I. look. Windows were usually simple.
6. Sliding windows with little square panes of glass - 18th cen.
7. Often the house was enlarged by the sweep of the roof carrying down in the rear, and creating an ell or continuous addition.
8. Floors (stones of house) are low.
9. Five windows across front on axis with openings below - one central door flanked by 2 windows on each side.
10. Next to the door, the most important feature of the house was the corner horizontal wooden brackets running length of house, front & back. ~~Very deep~~ ^{deep} overhang on this building.



23

Mr. & Mrs. Clarence Bennett
Original Use - Dwelling
Present - 2 family

Weatherboard
Circa 1880

Victorian 1835-1900
Fair Style
No or little change
Good condition



Present Owner - Mr. & Mrs. Emory Still

Original Use - Dwelling

Present Use - One family - Commercial

Material - Weatherboard

Year Built - Circa 1880

Victorian

Good style

Moderate Amount of change

Excellent condition

SOUTH SIDE OF MAIN STREET

beginning at entrance to Hahn

Transportation and running East

to Federal Street.



Present owner - Mr. & Mrs. Ollie Budge

Original Use - Dwelling

Present Use - 1 family

Material - Brick

Year Built - circa 1890

Victorian

Good style

No or little change

Good condition

M.



Present owner - Mr. & Mrs. Charles Wood

Present Use - Two Family - Commercial

Material - Brick

Year Built - Circa 1820

Federal

Poor Style

No or little change


Major repairs needed

Description

1. May be called a "double house," which became popular after 1815.

If porch were exaggeration of cornice with triangular pediment, this could be said, as 2 doors under one cornice became popular with double house.

2. Chimney at each end



Present Owner -

Mrs. Majie Perham

Present Use -

One family

Material - Brick

Year Built - circa 1800

Federal

Exceptional Style

Moderate Amount of Change

Needs Repairs

Run as an early inn.
Early Blacksmith shop
on the premises torn
down 1945.

Description

1. Triangular pediment

2. Two interior end chimneys


3. Brick

4. Wrought iron railings on porch

5. Work on fanlight over door. (appearance of columns at door)

6. Type of window similar to window type (John Holden Green buildings) in Providence, R.I. look.

7. Area over antique shop door similar to window type designs - block





P.

Present Owner - Mr. & Mrs. Franklin Shaw

Original Use - Dwelling

Present Use - One Family

Material - Brick

Year Built - West Wing circa 1830

East Wing early Twentieth Century

Federal

Victorian

Fair Style

Moderate Amount of Change

Needs Repairs

5 2 1/2
8 1



Present Owner - Mr. & Mrs. Benjamin D. Palmer

Original Use - Dwelling

Present Use - One Family

Material - Brick

Year Built - circa 1800

Post Colonial 1775-1800


Excellent Style

No or little change

Excellent Condition

Description

1. Designs over windows are examples in Providence, R.I. book.
2. Small roof over porch.
3. Three chimneys - one at each end, one centrally located - typical of Federal period.
4. Brick, although red was popular in Post-Colonial period, creamy yellow was used in Federal period. - this house is yellow brick.



Mr. Stoll N. Kemp

Original Use - Dwelling

Present Use - One family

Material - Brick

Year Built - circa 1800

Federal 1800-1830

Exceptional style

Moderate Amount

Excellent condition

Description

1. Made of red brick

2. Two interior chimneys, end.

3. Curves, festoons, interlaces on exterior cornices.

4. Lanlight door with columns.

5. Stone steps (brick) with wrought iron railings.

6. Flat headed arches over windows (End blocks with raised block in center.)

7. Some windows are smaller.

8. Type of shutters are typical.